
Star-Oddi LC–A1–1 75m T
MicroCat LC–A1–2 150m C/T/P
Hugrun LC–A1–3 250m T
Hugrun LC–A1–4 350m T
ADCP LC–A1–5 450m T/P
Star-Oddi LC–A1–6 525m T
S-4 LC–A1–7 600m T/S
No Data, Watchdog Timeout, Firmware Mismatch
MicroCat LC–A1–8 750m C/T/P
Cracked Connector, Flooded
RCM7 LC–A1–9 900m T/P
Rotor Stall
Star-Oddi LC–A1–10 1100m T
RCM8 LC–A1–11 1300m T/P
Star-Oddi LC–A1–12 1500m T
RCM11 LC–A1–13 2000m T/P
RCM11 LC–A1–14 2935m T
Star-Oddi LC–A2–1 75m T
MicroCat LC–A2–2 150m T/P
Hugrun LC–A2–3 250m T
Hugrun LC–A2–4 350m T
No Data
ADCP LC–A2–5 450m T/P
Star-Oddi LC–A2–6 525m T
S-4 LC–A2–7 600m T/S
MicroCat LC–A2–8 750m C/T/P
RCM7 LC–A2–9 900m T/P
Star-Oddi LC–A2–10 1100m T
RCM8 LC–A2–11 1300m T/P
Star-Oddi LC–A2–12 1500m T
RCM11 LC–A2–13 2000m T/P
RCM11 LC–A2–14 3100m T
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011


Star-Oddi LC-A3-1 75m T
Lost at Recovery During Towing of Mooring
MicroCat LC-A3-2 150m T/P
Hugrun LC-A3-3 250m T
No Data
Hugrun LC-A3-4 350m T
ADCP LC-A3-5 450m T/P
Star-Oddi LC-A3-6 525m T
S-4 LC-A3-7 600m T
Noisy, not concatenated
Power failure
MicroCat LC-A3-8 750m C/T/P
RCM7 LC-A3-9 900m T/P
Star-Oddi LC-A3-10 1100m T
RCM8 LC-A3-11 1300m T/P
Star-Oddi LC-A3-12 1500m T
RCM11 LC-A3-13 2000m T
RCM11 LC-A3-14 3193m T
Star-Oddi LC-A4-1 75m T
MicroCat LC-A4-2 150m C/T/P
Hugrun LC-A4-3 250m T
Hugrun LC-A4-4 350m T
ADCP LC-A4-5 450m T/P
Star-Oddi LC-A4-6 525m T
S-4 LC-A4-7 600m T
MicroCat LC-A4-8 750m C/T/P
Rotor Stall
RCM7 LC-A4-9 900m T
Star-Oddi LC-A4-10 1100m T
RCM8 LC-A4-11 1300m T/P
Star-Oddi LC-A4-12 1500m T
RCM11 LC-A4-13 2000m T/P
RCM11 LC-A4-14 3162m T
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011


Star-Oddi LC-B1-1 75m T
WHADCP LC-B1-G 90m T
MicroCat LC-B1-2 150m C/T/P
Hugrun LC-B1-3 250m T
Hugrun LC-B1-4 350m T
ADCP LC-B1-5 450m T/P
Star-Oddi LC-B1-6 525m T
RCM8 LC-B1-20 599m T
S-4 LC-B1-7 600m T
MicroCat LC-B1-8 750m C/T
RCM7 LC-B1-9 900m T
Star-Oddi LC-B1-10 1100m T
RCM8 LC-B1-11 1300m T/P
Star-Oddi LC-B1-12 1500m T
RCM11 LC-B1-13 1990m T/P
RCM11 LC-B1-14 2949m T
Star-Oddi LC-B2-1 75m T
RCM11 LC-B2-18 90m T
MicroCat LC-B2-2 150m C/T/P
Hugrun LC-B2-3 250m T
Hugrun LC-B2-4 350m T
ADCP LC-B2-5 450m T/P
Star-Oddi LC-B2-6 525m T
S-4 LC-B2-7 600m T
SBE56 LC-B2-19 600m T
MicroCat LC-B2-8 750m C/T/P
RCM7 LC-B2-9 900m T/P
Star-Oddi LC-B2-10 1100m T
RCM8 LC-B2-11 1300m T/P
Star-Oddi LC-B2-12 1500m T
RCM11 LC-B2-13 2000m T/P
RCM11 LC-B2-14 3032m T
No Data
Flooded
Power failure
Pressure Bad
Some Rotor Binding
Flooded
Power Failure
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011


Star-Oddi LC-B3-1 75m T
MicroCat LC-B3-2 150m C/T/P
Hugrun LC-B3-3 250m T
Hugrun LC-B3-4 350m T
ADCP LC-B3-5 450m T/P
Star-Oddi LC-B3-6 525m T
S-4 LC-B3-7 600m T
MicroCat LC-B3-8 750m C/T/P
RCM7 LC-B3-9 900m T
Star-Oddi LC-B3-10 1100m T
RCM8 LC-B3-11 1300m T/P
Star-Oddi LC-B3-12 1500m T
RCM11 LC-B3-13 2000m T/P
RCM11 LC-B3-14 3056m T
Flooded
Noisy Currents
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011


Star-Oddi LC-C1-1 75m T
MicroCat LC-C1-2 150m C/T/P
Hugrun LC-C1-3 250m T
Hugrun LC-C1-4 350m T
ADCP LC-C1-5 450m T/P
Star-Oddi LC-C1-6 525m T
S-4 LC-C1-7 600m T/S
Watchdog Timeout, Firmware Mismatch
T only
Power loss
MicroCat LC-C1-8 750m C/T/P
RCM7 LC-C1-9 900m T/P
Star-Oddi LC-C1-10 1100m T
RCM8 LC-C1-11 1300m T/P
Star-Oddi LC-C1-12 1500m T
RCM11 LC-C1-13 2000m T
RCM11 LC-C1-14 3082m T
Star-Oddi LC-C2-1 75m T
MicroCat LC-C2-2 150m C/T/P
Hugrun LC-C2-3 250m T
Hugrun LC-C2-4 350m T
ADCP LC-C2-5 450m T/P
Star-Oddi LC-C2-6 525m T
S-4 LC-C2-7 600m T
MicroCat LC-C2-8 750m C/T/P
RCM7 LC-C2-9 900m T/P
Some Rotor Stalls
Rotor Stalls
Star-Oddi LC-C2-10 1100m T
RCM8 LC-C2-11 1300m T
Flooded
Rotor Stalls
Star-Oddi LC-C2-12 1500m T
RCM11 LC-C2-13 2000m T
RCM11 LC-C2-14 3150m T
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011


RCM8 LC-D1 2727m T
RCM8 LC-D1A 2728m T
RCM8 LC-D2 2785m T
RCM8 LC-D3 2998m T
RCM8 LC-D4 3157m T
RCM8 LC-D5 3133m T
RCM8 LC-D7 3211m T
RCM8 LC-D8 3209m T
Mooring not yet recovered
Mooring not deployed for Depl 2
Mooring Parted, RCM Recovered near Key West
Mooring not yet recovered
A M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N
2009
2010
2011